

OSA -0599-68

7 February 1968

25X1A

To:

Subject: LOCAL MODIFICATION TO P/N DN55000 PARACHUTE

Dear Bruce,

Enclosed photos show a modification incorporated to one DN55000 Parachute, by BW-4 personnel.

The modification consists of a four-inch extension to the non-structural fabric beneath the two vertical lift webs.

This modification was required in order to permit length adjustment of the lift webbing on pilot


Prior to the modification, the fabric limited the harness length adjustment and put intolerable pressure on Bob's shoulders.

Sincerely,

25X1A

pac

Enclosures: Photos #18414 and #18413



ENVELOPE # 6115 -1

NEG. NO. 184/13


DATE SHOT DEC 14 1967

DATE RE-ENTERED _____

ORDERED BY



25X1A



ENVELOPE # 6115-2
NEG. NO. 18414
DATE SHOT DEC 14 1967
DATE RECEIVED
ORDERED BY

25X1A



ENVELOPE # 6115-1


NEG. NO. 18413


DATE SHOT DEC 14 1967

DATE REPRODUCED
ORDERED



25X1A



ENVELOPE # 6115-1
NEG. NO. 18413
DATE SHOT DEC 14 1967
DATE REPRINTED
ORDERED BY 


25X1A



ENVELOPE # 6115-21
NEG. NO. 18414
DATE SHOT DEC 14 1967
DATE REPRODUCED
ORDERED BY

25X1A



ENVELOPE # 6115-2
NEG. NO. 18414
DATE SHOT DEC 14 1967
DATE RECEIVED
ORDERED BY 

25X1A